

NO. INDEKS	JENIS / NAMA BARANG	SATUAN	HARGA
5 . 9	PERALATAN KENDARAAN BERMOTOR		
5 . 9 . 1	ACCU / BATTERY		
5 . 9 . 1 . 1	Accu Basah		
5 . 9 . 1 . 1 . 1	- 6 V - 4 A	buah	98,000
5 . 9 . 1 . 1 . 2	- 6 V - 5 A	buah	134,000
5 . 9 . 1 . 1 . 3	- 6 V - 5,5 A	buah	159,000
5 . 9 . 1 . 1 . 4	- 6 V - 6 A	buah	195,000
5 . 9 . 1 . 1 . 5	- 6 V - 10 A	buah	249,000
5 . 9 . 1 . 1 . 6	- 6 V - 11 A	buah	273,000
5 . 9 . 1 . 1 . 7	- 12 V - 2,5 A	buah	114,000
5 . 9 . 1 . 1 . 8	- 12 V - 3 A	buah	240,000
5 . 9 . 1 . 1 . 9	- 12 V - 3,5 A	buah	247,000
5 . 9 . 1 . 1 . 10	- 12 V - 4 A	buah	273,000
5 . 9 . 1 . 1 . 11	- 12 V - 5 A	buah	303,000
5 . 9 . 1 . 1 . 12	- 12 V - 5,5 A	buah	328,000
5 . 9 . 1 . 1 . 13	- 12 V - 7 A	buah	351,000
5 . 9 . 1 . 1 . 14	- 12 V - 8 A	buah	367,000
5 . 9 . 1 . 1 . 15	- 12 V - 9 A	buah	419,000
5 . 9 . 1 . 1 . 16	- 12 V - 10 A	buah	455,000
5 . 9 . 1 . 1 . 17	- 12 V - 11 A	buah	539,000
5 . 9 . 1 . 1 . 18	- 12 V - 12 A	buah	562,000
5 . 9 . 1 . 1 . 19	- 12 V - 14 A	buah	598,000
5 . 9 . 1 . 1 . 20	- 12 V - 26 A	buah	624,000
5 . 9 . 1 . 1 . 21	- 12 V - 32 A	buah	658,000
5 . 9 . 1 . 1 . 22	- 12 V - 33 A	buah	708,000
5 . 9 . 1 . 1 . 23	- 12 V - 35 A	buah	722,000
5 . 9 . 1 . 1 . 24	- 12 V - 40 A	buah	736,000
5 . 9 . 1 . 1 . 25	- 12 V - 45 A	buah	1,000,000
5 . 9 . 1 . 1 . 26	- 12 V - 50 A	buah	865,000
5 . 9 . 1 . 1 . 27	- 12 V - 55 A	buah	1,255,000
5 . 9 . 1 . 1 . 28	- 12 V - 60 A	buah	1,313,000
5 . 9 . 1 . 1 . 29	- 12 V - 65 A	buah	1,408,000
5 . 9 . 1 . 1 . 30	- 12 V - 70 A	buah	1,456,000
5 . 9 . 1 . 1 . 31	- 12 V - 75 A	buah	1,560,000
5 . 9 . 1 . 1 . 32	- 12 V - 80 A	buah	1,676,000
5 . 9 . 1 . 1 . 33	- 12 V - 100 A	buah	2,307,000
5 . 9 . 1 . 1 . 34	- 12 V - 120 A	buah	2,405,000
5 . 9 . 1 . 1 . 35	- 12 V - 150 A	buah	2,542,000
5 . 9 . 1 . 1 . 36	- 12 V - 170 A	buah	3,154,000
5 . 9 . 1 . 1 . 37	- 12 V - 200 A	buah	3,309,000
5 . 9 . 1 . 2	Accu MF		
5 . 9 . 1 . 2 . 1	- 12 V - 3 A	buah	240,000
5 . 9 . 1 . 2 . 2	- 12 V - 3,5 A	buah	247,000
5 . 9 . 1 . 2 . 3	- 12 V - 4 A	buah	333,000
5 . 9 . 1 . 2 . 4	- 12 V - 5 A	buah	364,000
5 . 9 . 1 . 2 . 5	- 12 V - 5,5 A	buah	455,000
5 . 9 . 1 . 2 . 6	- 12 V - 6 A	buah	524,000
5 . 9 . 1 . 2 . 7	- 12 V - 8 A	buah	648,000
5 . 9 . 1 . 2 . 8	- 12 V - 30 A	buah	732,000
5 . 9 . 1 . 2 . 9	- 12 V - 32 A	buah	848,000
5 . 9 . 1 . 2 . 10	- 12 V - 33 A	buah	912,000
5 . 9 . 1 . 2 . 11	- 12 V - 35 A	buah	949,000
5 . 9 . 1 . 2 . 12	- 12 V - 45 A	buah	988,000
5 . 9 . 1 . 2 . 13	- 12 V - 50 A	buah	1,052,000
5 . 9 . 1 . 2 . 14	- 12 V - 60 A	buah	1,224,000
5 . 9 . 1 . 2 . 15	- 12 V - 65 A	buah	1,814,000
5 . 9 . 1 . 2 . 16	- 12 V - 70 A	buah	1,833,000
5 . 9 . 1 . 2 . 17	- 12 V - 75 A	buah	1,898,000
5 . 9 . 1 . 2 . 18	- 12 V - 80 A	buah	2,223,000
5 . 9 . 1 . 3	Accu Hybrid		
5 . 9 . 1 . 3 . 1	- 12 V - 32 A		689,000
5 . 9 . 1 . 3 . 2	- 12 V - 33 A		743,000
5 . 9 . 1 . 3 . 3	- 12 V - 35 A		774,000
5 . 9 . 1 . 3 . 4	- 12 V - 45 A		804,000
5 . 9 . 1 . 3 . 5	- 12 V - 50 A		855,000
5 . 9 . 1 . 3 . 6	- 12 V - 60 A		992,000
5 . 9 . 1 . 3 . 7	- 12 V - 65 A		1,484,000
5 . 9 . 1 . 3 . 8	- 12 V - 70 A		1,560,000
5 . 9 . 1 . 3 . 9	- 12 V - 75 A		1,625,000
5 . 9 . 1 . 4	Air Accu	botol	22,000
5 . 9 . 2	Oli		
5 . 9 . 2 . 1	- 0,7	/Liter	40,000
5 . 9 . 2 . 2	- 0,8	/Liter	60,000
5 . 9 . 2 . 3	- 1	/Liter	182,000
5 . 9 . 3	B A N :		
5 . 9 . 3 . 1	Ban Luar Mobil / Bus / Truck:		
5 . 9 . 3 . 1 . 1	- R13	buah	1,250,000
5 . 9 . 3 . 1 . 2	- R14	buah	2,000,000

NO. INDEKS	JENIS / NAMA BARANG	SATUAN	HARGA
5 . 9 . 3 . 1 . 3	- R15	buah	2,500,000
5 . 9 . 3 . 1 . 4	- R16	buah	3,000,000
5 . 9 . 3 . 1 . 5	- R17	buah	3,500,000
5 . 9 . 3 . 1 . 6	- R18	buah	4,350,000
5 . 9 . 3 . 1 . 7	- R19	buah	5,000,000
5 . 9 . 3 . 1 . 8	- R20	buah	6,500,000
5 . 9 . 3 . 2	Ban Depan Hollan		
5 . 9 . 3 . 2 . 1	- 10.5 Ring 18 - 10 Ply	buah	5,507,000
5 . 9 . 3 . 2 . 2	- 10.5 Ring / 80 - 18	buah	7,605,000
5 . 9 . 3 . 2 . 3	- 10.5 Ring 18 - 12 Ply	buah	7,605,000
5 . 9 . 3 . 2 . 4	- 75.0 Ring 16 - 14 Ply	buah	2,535,000
5 . 9 . 3 . 3	Whellodear		
5 . 9 . 3 . 3 . 1	- 12.00 Ring 24 - 18 Ply	buah	11,645,000
5 . 9 . 3 . 4	Hollan & JCB (Excavator Loadear)		
5 . 9 . 3 . 4 . 1	- 16.9 Ring 28 - 10 Ply	buah	16,478,000
5 . 9 . 3 . 4 . 2	- 16.9 Ring 28 - 12 Ply	buah	17,898,000
5 . 9 . 3 . 4 . 3	- 16.9 Ring 28 - 14 Ply	buah	19,773,000
5 . 9 . 3 . 4 . 3	- Doosan 9.00-20	buah	3,572,120
5 . 9 . 3 . 5	Sepeda Motor		
5 . 9 . 3 . 5 . 1	- R 8	buah	170,000
5 . 9 . 3 . 5 . 2	- R 10	buah	230,000
5 . 9 . 3 . 5 . 3	- R 14	buah	300,000
5 . 9 . 3 . 5 . 4	- R 16	buah	350,000
5 . 9 . 3 . 5 . 5	- R 17	buah	400,000
5 . 9 . 3 . 5 . 6	- R 18	buah	550,000
5 . 9 . 3 . 5 . 7	- R 19	buah	570,000
5 . 9 . 3 . 5 . 8	- R 21	buah	600,000
5 . 9 . 3 . 6	Ban Dalam Mobil / Bus / Truck:		
5 . 9 . 3 . 6 . 1	- R 13	buah	260,000
5 . 9 . 3 . 6 . 2	- R 14	buah	377,500
5 . 9 . 3 . 6 . 3	- R 15	buah	415,000
5 . 9 . 3 . 6 . 4	- R 16	buah	530,000
5 . 9 . 3 . 6 . 5	R 17	buah	620,000
5 . 9 . 3 . 6 . 6	- R 18	buah	700,000
5 . 9 . 3 . 6 . 7	R 19	buah	780,000
5 . 9 . 3 . 6 . 8	- R 20	buah	879,600
5 . 9 . 3 . 7	Sepeda Motor		
5 . 9 . 3 . 7 . 1	- R 8	buah	50,000
5 . 9 . 3 . 7 . 2	- R 10	buah	50,000
5 . 9 . 3 . 7 . 3	- R 14	buah	50,000
5 . 9 . 3 . 7 . 4	- R 16	buah	50,000
5 . 9 . 3 . 7 . 5	- R 17	buah	50,000
5 . 9 . 3 . 7 . 6	- R 18	buah	80,000
5 . 9 . 3 . 7 . 7	- R 19	buah	110,000
5 . 9 . 3 . 7 . 8	- R 21	buah	150,000
5 . 9 . 4	Air Radiator		165,000
5 . 9 . 5	SUKU CADANG		
5 . 9 . 5 . 1	TRUCK CRANE ISUZU ELF NKR 66		
5 . 9 . 5 . 1 . 1	- Filter Oli	buah	155,400
5 . 9 . 5 . 1 . 2	- Filter Solar	buah	97,700
5 . 9 . 5 . 1 . 3	- Oli Engine	buah	49,400
5 . 9 . 5 . 1 . 4	- Filter Udara	buah	291,900
5 . 9 . 5 . 1 . 5	- Filter Hydraulic	buah	427,400
5 . 9 . 5 . 1 . 6	- Kampas Kopling	buah	1,553,000
5 . 9 . 5 . 1 . 7	- Pressure Cluth	buah	1,164,500
5 . 9 . 5 . 1 . 8	- Drug Bearing	buah	631,100
5 . 9 . 5 . 1 . 9	- Master Coupling Up	buah	369,600
5 . 9 . 5 . 1 . 10	- Master Coupling Down	buah	291,900
5 . 9 . 5 . 1 . 11	- Mounting Transmition	buah	233,100
5 . 9 . 5 . 1 . 12	- Batery	buah	1,455,300
5 . 9 . 5 . 1 . 13	- Relay 5 kaki	buah	146,000
5 . 9 . 5 . 1 . 14	- Relay 4 kaki	buah	116,600
5 . 9 . 5 . 1 . 15	- Haed Lamp Double	buah	291,900
5 . 9 . 5 . 1 . 16	- Head Lamp Single	buah	233,100
5 . 9 . 5 . 1 . 17	- Stop Lamp	set	408,500
5 . 9 . 5 . 1 . 18	- Fuse 10 Amp	buah	10,500
5 . 9 . 5 . 1 . 19	- Fuse 15 Amp	buah	10,500
5 . 9 . 5 . 1 . 20	- Fuse 20 Amp	buah	10,500
5 . 9 . 5 . 1 . 21	- Alternator	buah	2,910,600
5 . 9 . 5 . 1 . 22	- Motor Stater	buah	3,395,700
5 . 9 . 5 . 1 . 23	- Horn	set	485,100
5 . 9 . 5 . 1 . 24	- Knalpot	set	1,455,300
5 . 9 . 5 . 1 . 25	- Karet Gandul	buah	291,900
5 . 9 . 5 . 1 . 26	- Ring Velg	buah	679,400
5 . 9 . 5 . 1 . 27	- Per Depan	set	1,262,100
5 . 9 . 5 . 1 . 28	- Per Belakang	set	2,425,500
5 . 9 . 5 . 1 . 29	- Sock Breaker Depan	set	1,164,500
5 . 9 . 5 . 1 . 30	- Sock Breaker Belakang	set	1,358,700

NO. INDEKS	JENIS / NAMA BARANG	SATUAN	HARGA
5 . 9 . 5 . 1 . 31	- U Join	buah	605,900
5 . 9 . 5 . 1 . 32	- Wiper	ls	146,000
5 . 9 . 5 . 1 . 33	- Sling (Wire rope)	mtr	127,100
5 . 9 . 5 . 1 . 34	- Roller Bearing	buah	291,900
5 . 9 . 5 . 1 . 35	- Perbaiki Radiator	ls	388,500
5 . 9 . 5 . 1 . 36	- Perbaiki Alternator	ls	485,100
5 . 9 . 5 . 1 . 37	- Perbaiki Motor Stater	ls	485,100
5 . 9 . 5 . 2	TRUCK ISUZU ELF NHR 55		
5 . 9 . 5 . 2 . 1	- Filter Oli	buah	130,200
5 . 9 . 5 . 2 . 2	- Filter Oli By Pass	buah	92,400
5 . 9 . 5 . 2 . 3	- Filter Solar	buah	92,400
5 . 9 . 5 . 2 . 4	- Filter Udara	buah	277,200
5 . 9 . 5 . 2 . 5	- Kampas Kopling	buah	1,016,400
5 . 9 . 5 . 2 . 6	- Pressure Cluth	buah	831,600
5 . 9 . 5 . 2 . 7	- Drug Bearing	buah	600,600
5 . 9 . 5 . 2 . 8	- Master Coupling Up	buah	323,400
5 . 9 . 5 . 2 . 9	- Master Coupling Down	buah	184,800
5 . 9 . 5 . 2 . 10	- Mounting Transmition	buah	222,600
5 . 9 . 5 . 2 . 11	- Relay 5 kaki	buah	138,600
5 . 9 . 5 . 2 . 12	- Relay 4 kaki	buah	111,300
5 . 9 . 5 . 2 . 13	- Haed Lamp Double	buah	277,200
5 . 9 . 5 . 2 . 14	- Head Lamp Single	buah	222,600
5 . 9 . 5 . 2 . 15	- Stop Lamp	set	388,500
5 . 9 . 5 . 2 . 16	- Fuse 10 Amp	buah	9,500
5 . 9 . 5 . 2 . 17	- Fuse 15 Amp	buah	9,500
5 . 9 . 5 . 2 . 18	- Fuse 20 Amp	buah	9,500
5 . 9 . 5 . 2 . 19	- Alternator	buah	2,772,000
5 . 9 . 5 . 2 . 20	- Motor Stater	buah	3,234,000
5 . 9 . 5 . 2 . 21	- Horn	set	462,000
5 . 9 . 5 . 2 . 22	- Piston	buah	646,800
5 . 9 . 5 . 2 . 23	- Liner	buah	554,400
5 . 9 . 5 . 2 . 24	- Ring Piston	set	2,310,000
5 . 9 . 5 . 2 . 25	- Main Bearing	set	924,000
5 . 9 . 5 . 2 . 26	- Con Rod Bearing	set	739,200
5 . 9 . 5 . 2 . 27	- Trust Bearing	set	415,800
5 . 9 . 5 . 2 . 28	- Gasket OH	set	2,494,800
5 . 9 . 5 . 2 . 29	- Radiator	buah	3,696,000
5 . 9 . 5 . 2 . 30	- V Belt	buah	176,400
5 . 9 . 5 . 2 . 31	- Knalpot	set	1,478,400
5 . 9 . 5 . 2 . 32	- Per Depan	set	924,000
5 . 9 . 5 . 2 . 33	- Per Belakang	set	1,108,800
5 . 9 . 5 . 2 . 34	- Sock Breaker Depan	set	646,800
5 . 9 . 5 . 2 . 35	- Sock Breaker Belakang	set	785,400
5 . 9 . 5 . 2 . 36	- U Join	buah	582,800
5 . 9 . 5 . 2 . 37	- Wiper	ls	138,600
5 . 9 . 5 . 2 . 38	- Perbaiki Radiator	ls	369,600
5 . 9 . 5 . 2 . 39	- Perbaiki Alternator	ls	462,000
5 . 9 . 5 . 2 . 40	- Perbaiki Motor Stater	ls	462,000
5 . 9 . 5 . 2 . 41	- Engine Over Houll	ls	2,310,000
5 . 9 . 5 . 2 . 42	- Perbaiki Jog	ls	2,956,800
5 . 9 . 5 . 3	DUMP TRUCK DAIHATSU V 82 RH		
5 . 9 . 5 . 3 . 1	- Filter Oli	buah	144,900
5 . 9 . 5 . 3 . 2	- Filter Solar	buah	111,300
5 . 9 . 5 . 3 . 3	- Oli Enginer	Ltr	46,200
5 . 9 . 5 . 3 . 4	- Filter Udara	buah	184,800
5 . 9 . 5 . 3 . 5	- Kampas Kopling	buah	1,293,600
5 . 9 . 5 . 3 . 6	- Pressure Cluth	buah	831,600
5 . 9 . 5 . 3 . 7	- Drug Bearing	buah	554,400
5 . 9 . 5 . 3 . 8	- Master Coupling Up	buah	388,500
5 . 9 . 5 . 3 . 9	- Master Coupling Down	buah	296,100
5 . 9 . 5 . 3 . 10	- Mounting Transmition	buah	259,400
5 . 9 . 5 . 3 . 11	- Gigi-renteng	set	10,182,900
5 . 9 . 5 . 3 . 12	- Batery	buah	1,974,000
5 . 9 . 5 . 3 . 13	- Relay 5 kaki	buah	138,600
5 . 9 . 5 . 3 . 14	- Relay 4 kaki	buah	111,300
5 . 9 . 5 . 3 . 15	- Haed Lamp Double	buah	277,200
5 . 9 . 5 . 3 . 16	- Head Lamp Single	buah	222,600
5 . 9 . 5 . 3 . 17	- Stop Lamp	set	369,600
5 . 9 . 5 . 3 . 18	- Fuse 10 Amp	buah	9,500
5 . 9 . 5 . 3 . 19	- Fuse 15 Amp	buah	9,500
5 . 9 . 5 . 3 . 20	- Fuse 20 Amp	buah	9,500
5 . 9 . 5 . 3 . 21	- Alternator	buah	2,772,000
5 . 9 . 5 . 3 . 22	- Motor Stater	buah	3,234,000
5 . 9 . 5 . 3 . 23	- Horn	set	462,000
5 . 9 . 5 . 3 . 24	- Piston	buah	600,600
5 . 9 . 5 . 3 . 25	- Liner	buah	573,300
5 . 9 . 5 . 3 . 26	- Ring Piston	set	974,400
5 . 9 . 5 . 3 . 27	- Main Bearing	set	758,100
5 . 9 . 5 . 3 . 28	- Con Rod Bearing	set	592,200
5 . 9 . 5 . 3 . 29	- Trust Bearing	set	462,000

NO. INDEKS	JENIS / NAMA BARANG	SATUAN	HARGA
5 . 9 . 5 . 3 . 30	- Gasket OH	set	2,310,000
5 . 9 . 5 . 3 . 31	- Radiator	buah	6,468,000
5 . 9 . 5 . 3 . 32	- V Belt	buah	101,900
5 . 9 . 5 . 3 . 33	- Water Pump	buah	831,600
5 . 9 . 5 . 3 . 34	- Engine Mounting	buah	184,800
5 . 9 . 5 . 3 . 35	- Ban Luar/ Dalam / Sliwer	buah	3,141,600
5 . 9 . 5 . 3 . 36	- Knalpot	set	1,386,000
5 . 9 . 5 . 3 . 37	- Karet Gandul	buah	240,500
5 . 9 . 5 . 3 . 38	- Ring Velg	buah	646,800
5 . 9 . 5 . 3 . 39	- Kabel PTO 2,5 Mtr	buah	739,200
5 . 9 . 5 . 3 . 40	- Kabel PTO 3,5 Mtr	buah	831,600
5 . 9 . 5 . 3 . 41	- Per Depan	set	1,201,200
5 . 9 . 5 . 3 . 42	- Per Belakang	set	2,310,000
5 . 9 . 5 . 3 . 43	- Sock Breaker Depan	set	1,108,800
5 . 9 . 5 . 3 . 44	- Sock Breaker Belakang	set	1,293,600
5 . 9 . 5 . 3 . 45	- U Joint PTO	buah	277,200
5 . 9 . 5 . 3 . 46	- Tabung Knalpot	buah	462,000
5 . 9 . 5 . 3 . 47	- Pipa Knalpot Atas	buah	415,800
5 . 9 . 5 . 3 . 48	- Master Rem Depan	buah	240,500
5 . 9 . 5 . 3 . 49	- Master Rem Belakang	buah	296,100
5 . 9 . 5 . 3 . 50	- U Join Diferential	buah	699,300
5 . 9 . 5 . 3 . 51	- Wiper	ls	138,600
5 . 9 . 5 . 3 . 52	- Hose Hydroolic Dump In	buah	887,300
5 . 9 . 5 . 3 . 53	- Hose Hydroolic Dump Return	buah	646,800
5 . 9 . 5 . 3 . 54	- Perbaikan Radiator	ls	369,600
5 . 9 . 5 . 3 . 55	- Perbaikan Alternator	ls	462,000
5 . 9 . 5 . 3 . 56	- Perbaikan Motor Stater	ls	462,000
5 . 9 . 5 . 3 . 57	- Engine Over Houl	ls	2,772,000
5 . 9 . 5 . 3 . 58	- Perbaikan Jog	ls	2,772,000
5 . 9 . 5 . 4	DUMP TRUCK ISUZU ELF NKR 58		
5 . 9 . 5 . 4 . 1	- Filter Oli Main	buah	92,400
5 . 9 . 5 . 4 . 2	- Filter Oli By Pass	buah	101,900
5 . 9 . 5 . 4 . 3	- Filter Solar	buah	92,400
5 . 9 . 5 . 4 . 4	- Filter Oli Main	buah	92,400
5 . 9 . 5 . 4 . 5	- Filter Oli By Pass	buah	101,900
5 . 9 . 5 . 4 . 6	- Filter Solar	buah	92,400
5 . 9 . 5 . 4 . 7	- Filter Udara	buah	277,200
5 . 9 . 5 . 4 . 8	- Kampas Kopling	buah	1,478,400
5 . 9 . 5 . 4 . 9	- Pressure Cluth	buah	843,200
5 . 9 . 5 . 4 . 10	- Drug Bearing	buah	600,600
5 . 9 . 5 . 4 . 11	- Master Coupling Up	buah	323,400
5 . 9 . 5 . 4 . 12	- Master Coupling Down	buah	184,800
5 . 9 . 5 . 4 . 13	- Mounting Transmition	buah	222,600
5 . 9 . 5 . 4 . 14	- Batery	buah	1,386,000
5 . 9 . 5 . 4 . 15	- Relay 5 kaki	buah	138,600
5 . 9 . 5 . 4 . 16	- Relay 4 kaki	buah	111,300
5 . 9 . 5 . 4 . 17	- Haed Lamp Double	buah	277,200
5 . 9 . 5 . 4 . 18	- Head Lamp Single	buah	222,600
5 . 9 . 5 . 4 . 19	- Stop Lamp	set	388,500
5 . 9 . 5 . 4 . 20	- Fuse 10 Amp	buah	9,500
5 . 9 . 5 . 4 . 21	- Fuse 15 Amp	buah	9,500
5 . 9 . 5 . 4 . 22	- Fuse 20 Amp	buah	9,500
5 . 9 . 5 . 4 . 23	- Alternator	buah	2,772,000
5 . 9 . 5 . 4 . 24	- Motor Stater	buah	3,234,000
5 . 9 . 5 . 4 . 25	- Horn	set	462,000
5 . 9 . 5 . 4 . 26	- Piston	buah	739,200
5 . 9 . 5 . 4 . 27	- Liner	buah	554,400
5 . 9 . 5 . 4 . 28	- Ring Piston	set	2,494,800
5 . 9 . 5 . 4 . 29	- Main Bearing	set	1,108,800
5 . 9 . 5 . 4 . 30	- Con Rod Bearing	set	831,600
5 . 9 . 5 . 4 . 31	- Trust Bearing	set	415,800
5 . 9 . 5 . 4 . 32	- Gasket OH	set	2,735,300
5 . 9 . 5 . 4 . 33	- Radiator	buah	6,468,000
5 . 9 . 5 . 4 . 34	- V Belt	buah	176,400
5 . 9 . 5 . 4 . 35	- Ban Luar/ Dalam / Sliwer	buah	3,141,600
5 . 9 . 5 . 4 . 36	- Knalpot	set	1,386,000
5 . 9 . 5 . 4 . 37	- Karet Gandul	buah	277,200
5 . 9 . 5 . 4 . 38	- Ring Velg	buah	646,800
5 . 9 . 5 . 4 . 39	- Kabel PTO 2,5 Mtr	buah	739,200
5 . 9 . 5 . 4 . 40	- Kabel PTO 3,5 Mtr	buah	831,600
5 . 9 . 5 . 4 . 41	- Per Depan	set	1,201,200
5 . 9 . 5 . 4 . 42	- Per Belakang	set	2,310,000
5 . 9 . 5 . 4 . 43	- Sock Breaker Depan	set	1,108,800
5 . 9 . 5 . 4 . 44	- Sock Breaker Belakang	set	1,293,600
5 . 9 . 5 . 4 . 45	- Case, Real Axle	buah	20,328,000
5 . 9 . 5 . 4 . 46	- Shaft, Axle RR	buah	4,804,800
5 . 9 . 5 . 4 . 47	- U Joint PTO	buah	277,200
5 . 9 . 5 . 4 . 48	- U Join	buah	665,700
5 . 9 . 5 . 4 . 49	- Wiper	ls	138,600
5 . 9 . 5 . 4 . 50	- Hose Hydrooulic Dump In	buah	887,300

NO. INDEKS	JENIS / NAMA BARANG	SATUAN	HARGA
5 . 9 . 5 . 4 . 51	- Hose Hydroulic Dump Return	buah	646,800
5 . 9 . 5 . 4 . 52	- Perbaiki Radiator	ls	369,600
5 . 9 . 5 . 4 . 53	- Perbaiki Alternator	ls	462,000
5 . 9 . 5 . 4 . 54	- Perbaiki Motor Stater	ls	462,000
5 . 9 . 5 . 4 . 55	- Jasa Engine Over Houll	ls	2,887,500
5 . 9 . 5 . 4 . 56	- Perbaiki Jog	ls	2,402,400
5 . 9 . 5 . 5	WHEEL EXCAVATOR DAEWOO SOLAR 130 W- V - 2000		
5 . 9 . 5 . 5 . 1	- Filter Oli	buah	320,300
5 . 9 . 5 . 5 . 2	- Filter Solar	buah	223,700
5 . 9 . 5 . 5 . 3	- Filter Screen	buah	873,600
5 . 9 . 5 . 5 . 4	- Filter Pilot	buah	175,400
5 . 9 . 5 . 5 . 5	- Filter Brake	buah	97,700
5 . 9 . 5 . 5 . 6	- Filter Udara	buah	1,747,200
5 . 9 . 5 . 5 . 7	- Filter Hydraulic	buah	2,134,700
5 . 9 . 5 . 5 . 8	- Ban Luar/ Dalam / Sliwer	buah	8,731,800
5 . 9 . 5 . 5 . 9	- V Belt Set	set	727,700
5 . 9 . 5 . 5 . 10	- Tooth	buah	679,400
5 . 9 . 5 . 5 . 11	- Adapter Tooth	buah	679,400
5 . 9 . 5 . 5 . 12	- Cutter	buah	1,262,100
5 . 9 . 5 . 5 . 13	- Bolt	buah	58,800
5 . 9 . 5 . 5 . 14	- Pin Tooth	buah	49,400
5 . 9 . 5 . 5 . 15	- Coupling	buah	1,455,300
5 . 9 . 5 . 5 . 16	- Water Pump	buah	10,479,000
5 . 9 . 5 . 5 . 17	- Filter Pilot Brake Assy	set	11,642,400
5 . 9 . 5 . 5 . 18	- Brake Pump/PTO Pump	set	69,854,400
5 . 9 . 5 . 5 . 19	- Hose Pilot	buah	1,455,300
5 . 9 . 5 . 5 . 20	- Hose Transmision	buah	1,310,400
5 . 9 . 5 . 5 . 21	- Hose Boom	buah	1,116,200
5 . 9 . 5 . 5 . 22	- Hose Dozer	buah	1,262,100
5 . 9 . 5 . 5 . 23	- Hose Main Pump	buah	1,436,400
5 . 9 . 5 . 5 . 24	- Hose Return	buah	1,125,600
5 . 9 . 5 . 5 . 25	- Hose Swing	buah	1,217,000
5 . 9 . 5 . 5 . 26	- Hose Arm	buah	747,600
5 . 9 . 5 . 5 . 27	- Seal Kit Boom	set	2,081,100
5 . 9 . 5 . 5 . 28	- Seal Kit Arm	set	2,271,200
5 . 9 . 5 . 5 . 29	- Seal Kit Bucket	set	1,803,900
5 . 9 . 5 . 5 . 30	- Seal Kit Dooser	set	1,526,700
5 . 9 . 5 . 5 . 31	- Seal Kit Transmision	set	13,844,300
5 . 9 . 5 . 5 . 32	- Seal Kit Central Join	set	2,065,400
5 . 9 . 5 . 5 . 33	- Seal Kit Control Valve	set	1,455,300
5 . 9 . 5 . 5 . 34	- Seal Kit main Pump	set	2,910,600
5 . 9 . 5 . 5 . 35	- Liner	buah	1,990,800
5 . 9 . 5 . 5 . 36	- Piston	buah	920,900
5 . 9 . 5 . 5 . 37	- Ring, Top	buah	1,578,200
5 . 9 . 5 . 5 . 38	- Ring, Second	buah	135,500
5 . 9 . 5 . 5 . 39	- Ring, Oil	buah	222,600
5 . 9 . 5 . 5 . 40	- Metal,Crank STD	buah	257,300
5 . 9 . 5 . 5 . 41	- Washer, Trust	buah	67,200
5 . 9 . 5 . 5 . 42	- Metal Con Rod STD	buah	135,500
5 . 9 . 5 . 5 . 43	- Seal, Mechanical	buah	665,700
5 . 9 . 5 . 5 . 44	- Bearing,Unit	buah	1,689,500
5 . 9 . 5 . 5 . 45	- Gasket,Cylinder Head	buah	2,237,600
5 . 9 . 5 . 5 . 46	- Gasket, Oil Fan	buah	657,300
5 . 9 . 5 . 5 . 47	- Gasket, Fly Wheel Housing	buah	184,800
5 . 9 . 5 . 5 . 48	- Seal, Crank Shaft Front	buah	104,000
5 . 9 . 5 . 5 . 49	- Alternator	buah	9,216,900
5 . 9 . 5 . 5 . 50	- Motor Stater	buah	10,672,200
5 . 9 . 5 . 5 . 51	- Solenoid Valve	buah	5,821,200
5 . 9 . 5 . 5 . 52	- Solenoid Pump	buah	6,791,400
5 . 9 . 5 . 5 . 53	- Perbaiki Radiator	ls	1,262,100
5 . 9 . 5 . 5 . 54	- Perbaiki Alternator	ls	582,800
5 . 9 . 5 . 5 . 55	- Perbaiki Motor Stater	ls	485,100
5 . 9 . 5 . 5 . 56	- Perbaiki Bucket	ls	9,314,600
5 . 9 . 5 . 5 . 57	- Motor E/G Control	ls	15,361,500
5 . 9 . 5 . 5 . 58	- Engine Over Houll	ls	9,702,000
5 . 9 . 5 . 5 . 59	- Setting Hydroulic System	ls	4,851,000
5 . 9 . 5 . 6	BEGHOE LOADER SCHAEFF SKB 902 - 1989		
5 . 9 . 5 . 6 . 1	- Filter Oli	buah	396,900
5 . 9 . 5 . 6 . 2	- Filter Solar	buah	298,200
5 . 9 . 5 . 6 . 3	- Screen Hydraulic	buah	1,288,400
5 . 9 . 5 . 6 . 4	- Filter Screen	buah	1,288,400
5 . 9 . 5 . 6 . 5	- Filter Udara	buah	546,000
5 . 9 . 5 . 6 . 6	- Filter Hydraulic	buah	743,400
5 . 9 . 5 . 6 . 7	- Ban Luar/ Dalam / Sliwer	buah	23,784,600
5 . 9 . 5 . 6 . 8	- V Belt Set	set	298,200
5 . 9 . 5 . 6 . 9	- Tooth	buah	595,400
5 . 9 . 5 . 6 . 10	- Adapter Tooth	buah	694,100
5 . 9 . 5 . 6 . 11	- Cutter	buah	1,288,400
5 . 9 . 5 . 6 . 12	- Bolt	buah	59,900
5 . 9 . 5 . 6 . 13	- Hose Pilot	buah	644,700

NO. INDEKS	JENIS / NAMA BARANG	SATUAN	HARGA
5 . 9 . 5 . 6 . 14	- Hose Transmision	buah	2,808,800
5 . 9 . 5 . 6 . 15	- Hose Boom	buah	2,164,100
5 . 9 . 5 . 6 . 16	- Hose Dozer	buah	1,031,100
5 . 9 . 5 . 6 . 17	- Hose Main Pump	buah	967,100
5 . 9 . 5 . 6 . 18	- Hose Return	buah	773,900
5 . 9 . 5 . 6 . 19	- Hose Swing	buah	1,243,200
5 . 9 . 5 . 6 . 20	- Hose Arm	buah	1,129,800
5 . 9 . 5 . 6 . 21	- Seal Kit Boom	set	2,062,200
5 . 9 . 5 . 6 . 22	- Seal Kit Arm	set	2,448,600
5 . 9 . 5 . 6 . 23	- Seal Kit Bucket	set	1,031,100
5 . 9 . 5 . 6 . 24	- Seal Kit Swing	set	1,546,700
5 . 9 . 5 . 6 . 25	- Seal Kit Boom Loader	set	2,448,600
5 . 9 . 5 . 6 . 26	- Seal Kit bucket Loader	set	1,546,700
5 . 9 . 5 . 6 . 27	- Seal Kit Jack	set	1,288,400
5 . 9 . 5 . 6 . 28	- Seal Kit main Pump	set	2,973,600
5 . 9 . 5 . 6 . 29	- Seal Kit Stering	set	2,576,700
5 . 9 . 5 . 6 . 30	- Liner	buah	2,032,800
5 . 9 . 5 . 6 . 31	- Piston	buah	940,800
5 . 9 . 5 . 6 . 32	- Ring Piston	buah	892,500
5 . 9 . 5 . 6 . 33	- Metal,Crank STD	buah	278,300
5 . 9 . 5 . 6 . 34	- Washer, Trust	buah	684,600
5 . 9 . 5 . 6 . 35	- Metal Con Rod STD	buah	238,400
5 . 9 . 5 . 6 . 36	- Gasket O H	buah	5,450,600
5 . 9 . 5 . 6 . 37	- Fuel Pump	buah	1,586,600
5 . 9 . 5 . 6 . 38	- Water Pump	buah	7,531,700
5 . 9 . 5 . 6 . 39	- Alternator	buah	6,937,400
5 . 9 . 5 . 6 . 40	- Motor Stater	buah	7,928,600
5 . 9 . 5 . 6 . 41	- Radiator	buah	15,856,100
5 . 9 . 5 . 6 . 42	- Selenoid Valve	buah	4,955,000
5 . 9 . 5 . 6 . 43	- Selenoid Pump	buah	5,946,200
5 . 9 . 5 . 6 . 44	- Perbaikan Radiator	Ls	991,200
5 . 9 . 5 . 6 . 45	- Perbaikan Alternator	Ls	595,400
5 . 9 . 5 . 6 . 46	- Perbaikan Motor Stater	Ls	495,600
5 . 9 . 5 . 6 . 47	- Bearing 32020	buah	1,514,100
5 . 9 . 5 . 6 . 48	- Niple Grease	buah	83,000
5 . 9 . 5 . 6 . 49	- Bushing Brown	buah	548,100
5 . 9 . 5 . 6 . 50	- As Bucket	buah	924,000
5 . 9 . 5 . 6 . 51	- Seal Clust 5072	buah	283,500
5 . 9 . 5 . 6 . 52	- Seal WDI	buah	223,700
5 . 9 . 5 . 6 . 53	- Seal Clust 60	buah	307,700
5 . 9 . 5 . 6 . 54	- Radiator Coolant	Ltr	112,400
5 . 9 . 5 . 6 . 55	- Seal Oli TTO TC 145-170	buah	132,300
5 . 9 . 5 . 6 . 56	- Perbaikan Bucket	Ls	6,937,400
5 . 9 . 5 . 6 . 57	- Engine Over Houll	Ls	7,928,600
5 . 9 . 5 . 6 . 58	- Setting Hyd Sistem	Ls	3,964,800
5 . 9 . 5 . 7 .	MITSUBSHI L300		
5 . 9 . 5 . 7 . 1	- Filter Oli	buah	184,800
5 . 9 . 5 . 7 . 2	- Filter Solar	buah	130,200
5 . 9 . 5 . 7 . 3	- Filter Udara	buah	222,600
5 . 9 . 5 . 7 . 4	- Kampas Kopling	buah	831,600
5 . 9 . 5 . 7 . 5	- Pressure Cluth	buah	1,108,800
5 . 9 . 5 . 7 . 6	- Drug Bearing	buah	462,000
5 . 9 . 5 . 7 . 7	- Master Coupling Up	buah	351,800
5 . 9 . 5 . 7 . 8	- Master Coupling Down	buah	277,200
5 . 9 . 5 . 7 . 9	- Mounting Transmition	buah	222,600
5 . 9 . 5 . 7 . 10	- Batery	buah	1,386,000
5 . 9 . 5 . 7 . 11	- Alternator	buah	2,217,600
5 . 9 . 5 . 7 . 12	- Motor Stater	buah	2,772,000
5 . 9 . 5 . 7 . 13	- Horn	set	369,600
5 . 9 . 5 . 7 . 14	- Knalpot	set	1,386,000
5 . 9 . 5 . 7 . 15	- Velg	buah	646,800
5 . 9 . 5 . 7 . 16	- Per Depan	set	1,201,200
5 . 9 . 5 . 7 . 17	- Per Belakang	set	2,310,000
5 . 9 . 5 . 7 . 18	- Sock Breaker Depan	set	1,478,400
5 . 9 . 5 . 7 . 19	- Sock Breaker Belakang	set	924,000
5 . 9 . 5 . 7 . 20	- U Join	buah	415,800
5 . 9 . 5 . 7 . 21	- Wiper	ls	138,600
5 . 9 . 5 . 7 . 22	- Perbaikan Radiator	ls	369,600
5 . 9 . 5 . 7 . 23	- Perbaikan Alternator	ls	462,000
5 . 9 . 5 . 7 . 24	- Perbaikan Motor Stater	ls	462,000
5 . 9 . 5 . 8	KOBELCO 7035 CRANE / CLAMPSEL 2000		
5 . 9 . 5 . 8 . 1	- Filter Oli	Buah	582,800
5 . 9 . 5 . 8 . 2	- Filter Solar	Buah	310,800
5 . 9 . 5 . 8 . 3	- Filter Screen	Buah	873,600
5 . 9 . 5 . 8 . 4	- Filter Udara	Buah	2,134,700
5 . 9 . 5 . 8 . 5	- Filter Hydraulic	Buah	1,747,200
5 . 9 . 5 . 8 . 6	- V Belt Set	Set	727,700
5 . 9 . 5 . 8 . 7	- Nozzle	Buah	1,212,800
5 . 9 . 5 . 8 . 8	- Ring piston	Set	1,116,200
5 . 9 . 5 . 8 . 9	- Gasket Kit	Buah	9,216,900

NO. INDEKS	JENIS / NAMA BARANG	SATUAN	HARGA
5 . 9 . 5 . 8 . 10	- Injection Pump(Kalibrasi)	Buah	11,060,700
5 . 9 . 5 . 8 . 11	- Piston Shoe	Set	24,255,000
5 . 9 . 5 . 8 . 12	- Shoe Plate	Set	8,246,700
5 . 9 . 5 . 8 . 13	- Block Side	Set	36,867,600
5 . 9 . 5 . 8 . 14	- Kit repair hyd pump main	Set	7,276,500
5 . 9 . 5 . 8 . 15	- Bearing	Buah	2,425,500
5 . 9 . 5 . 8 . 16	- Piston Shoe	Set	40,748,400
5 . 9 . 5 . 8 . 17	- Shoe Plate	Set	9,216,900
5 . 9 . 5 . 8 . 18	- Block Side	Set	37,837,800
5 . 9 . 5 . 8 . 19	- Kit repair hyd pump	Set	6,791,400
5 . 9 . 5 . 8 . 20	- Bolt Shoe	Set	8,246,700
5 . 9 . 5 . 8 . 21	- Nut Shoe	Set	5,433,800
5 . 9 . 5 . 8 . 22	- neppel grease	Buah	194,300
5 . 9 . 5 . 8 . 23	- Sling (Wire Rope)	Meter	175,400
5 . 9 . 5 . 9 .	ROAD ROLLER 6 TON		
5 . 9 . 5 . 9 . 1	Plate Kopling Maju	bh	1,138,000
5 . 9 . 5 . 9 . 2	Plate Kopling Mundur	bh	1,170,000
5 . 9 . 5 . 9 . 3	Laher Roda	bh	764,000
5 . 9 . 5 . 9 . 4	Seal Roda	bh	212,000
5 . 9 . 5 . 9 . 5	Cross Kouple	bh	1,365,000
5 . 9 . 5 . 9 . 6	Membran	bh	342,000
5 . 9 . 5 . 9 . 7	Fiber	bh	228,000
5 . 9 . 5 . 9 . 8	Filter Oli	bh	130,000
5 . 9 . 5 . 9 . 9	Filter Solar	bh	114,000
5 . 9 . 5 . 9 . 10	Tangan Gareng	bh	1,430,000
5 . 9 . 5 . 9 . 11	Garpu Kopling	bh	2,275,000
5 . 9 . 5 . 9 . 12	Boshing Roda	bh	602,000
5 . 9 . 5 . 9 . 13	Pinion	bh	2,763,000
5 . 9 . 5 . 9 . 14	Gigi Renteng	bh	16,250,000
5 . 9 . 5 . 10	ROAD ROLLER 8 TON		
5 . 9 . 5 . 10 . 1	Plate Kopling Maju	bh	1,300,000
5 . 9 . 5 . 10 . 2	Plate Kopling Mundur	bh	1,300,000
5 . 9 . 5 . 10 . 3	Laher Roda	bh	845,000
5 . 9 . 5 . 10 . 4	Seal Roda	bh	634,000
5 . 9 . 5 . 10 . 5	Cross Kouple	bh	1,690,000
5 . 9 . 5 . 10 . 6	Membran	bh	277,000
5 . 9 . 5 . 10 . 7	Fiber	bh	244,000
5 . 9 . 5 . 10 . 8	Filter Oli	bh	195,000
5 . 9 . 5 . 10 . 9	Filter Solar	bh	195,000
5 . 9 . 5 . 10 . 10	Tangan Gareng	bh	1,593,000
5 . 9 . 5 . 10 . 11	Garpu Kopling	bh	2,275,000
5 . 9 . 5 . 10 . 12	Boshing Roda	bh	1,300,000
5 . 9 . 5 . 10 . 13	Pinion	bh	3,088,000
5 . 9 . 5 . 10 . 14	Gigi Renteng	bh	16,250,000
5 . 9 . 5 . 11	TANDEM ROLLER 2 TON		
5 . 9 . 5 . 11 . 1	Oil Filter Element		
5 . 9 . 5 . 11 . 1 . 1	Filter Oli Hydraulic Suction	buah	293,000
5 . 9 . 5 . 11 . 1 . 2	Filter Solar	buah	244,000
5 . 9 . 5 . 11 . 2	Hydraulic Sistem		
5 . 9 . 5 . 11 . 2 . 1	Pompa Hidrolik	buah	1,317,000
5 . 9 . 5 . 11 . 2 . 2	Flex. Hose Pump Hidrolik	buah	878,000
5 . 9 . 5 . 11 . 3	Aux. Front and Rear		
5 . 9 . 5 . 11 . 3 . 1	Seal Roda Depan	buah	780,000
5 . 9 . 5 . 11 . 3 . 2	Seal Roda Belakang	buah	780,000
5 . 9 . 5 . 11 . 4	Engine		
5 . 9 . 5 . 11 . 4 . 1	V-Belt	buah	342,000
5 . 9 . 5 . 12	BABY ROLLER HYDROLIK		
5 . 9 . 5 . 12 . 1	Hydraulic Pump Component		
5 . 9 . 5 . 12 . 1 . 1	Piston Hidrolik	buah	13,650,000
5 . 9 . 5 . 12 . 2	Drum and Drive		
5 . 9 . 5 . 12 . 2 . 1	Laker Roda Depan	buah	1,170,000
5 . 9 . 5 . 12 . 2 . 2	Laker Roda Belakang	buah	1,170,000
5 . 9 . 5 . 12 . 2 . 3	Drivbelt	buah	244,000
5 . 9 . 5 . 12 . 2 . 4	Karet Pengetar	buah	537,000
5 . 9 . 5 . 12 . 3	Filter Element		
5 . 9 . 5 . 12 . 3 . 1	Filter Oli	buah	195,000
5 . 9 . 5 . 12 . 3 . 2	Filter Solar	buah	195,000
5 . 9 . 5 . 13 .	BABY ROLLER MANUAL		
5 . 9 . 5 . 13 . 1	Filter Element		
5 . 9 . 5 . 13 . 1 . 2	Filter Oli	buah	147,000
5 . 9 . 5 . 13 . 1 . 3	Filter Solar	buah	147,000
5 . 9 . 5 . 13 . 2	Engine and Fuel System		
5 . 9 . 5 . 13 . 2 . 1	Drivbelt	buah	98,000
5 . 9 . 5 . 13 . 2 . 2	Gelas Filter Solar	buah	98,000
5 . 9 . 5 . 14	VIBRO ROLLER COMBINED		
5 . 9 . 5 . 14 . 1	Filter Element		
5 . 9 . 5 . 14 . 1 . 1	Filter Oli	buah	293,000
5 . 9 . 5 . 14 . 1 . 2	Filter Solar	buah	293,000
5 . 9 . 5 . 14 . 2	Battery		
5 . 9 . 5 . 14 . 2 . 1	Accu	buah	1,658,000

NO. INDEKS	JENIS / NAMA BARANG	SATUAN	HARGA
5 . 9 . 5 . 14 . 3	Hydraulic Sistem		
5 . 9 . 5 . 14 . 3 . 1	Selang Hidrolik	buah	878,000
5 . 9 . 5 . 14 . 3 . 2	Pompa Air	buah	488,000
5 . 9 . 5 . 14 . 3 . 3	Teaming Belt	buah	244,000
5 . 9 . 5 . 15 .	TANDEM ROLLER 8 TON		
5 . 9 . 5 . 15 . 1	Lubricating Oil Pump		
5 . 9 . 5 . 15 . 1 . 1	Pompa Oli / Oil Pump Unit	buah	1,755,000
5 . 9 . 5 . 15 . 1 . 2	Selang Hidrolik/ Rubber Hose	buah	878,000
5 . 9 . 5 . 15 . 2	Steering Roll		
5 . 9 . 5 . 15 . 2 . 1	Laker Pemutar Roda / Bearing 7218	buah	2,438,000
5 . 9 . 5 . 15 . 3	Master Clutch		
5 . 9 . 5 . 15 . 3 . 1	Plate Kopleng / Driven Disk Assembly	buah	2,535,000
5 . 9 . 5 . 15 . 4	Second Shaft		
5 . 9 . 5 . 15 . 4 . 1	Disc Clute / Driven Friction Facing	buah	878,000
5 . 9 . 5 . 15 . 4 . 2	Disc Plate / Driven Friction Facing	buah	780,000
5 . 9 . 5 . 15 . 5	Filter Element		
5 . 9 . 5 . 15 . 5 . 1	Filter Oli	buah	293,000
5 . 9 . 5 . 15 . 5 . 2	Filter Solar	buah	293,000
5 . 9 . 5 . 15 . 5 . 3	Filter Udara	buah	293,000
5 . 9 . 5 . 15 . 6	Battery		
5 . 9 . 5 . 15 . 6 . 1	Accu	buah	2,438,000
5 . 9 . 5 . 16	KOMPRESOR 2 UNIT		
5 . 9 . 5 . 16 . 1 . 1	Separator / Element Air Filter Compressor	buah	7,313,000
5 . 9 . 5 . 16 . 1 . 2	Slang Angin	buah	1,950,000
5 . 9 . 5 . 16 . 1 . 3	Pisau Jack Hammer	buah	2,925,000
5 . 9 . 5 . 16 . 1 . 4	Seal Jack Hammer	buah	195,000
5 . 9 . 5 . 16 . 1 . 5	Accu	buah	2,438,000
5 . 9 . 5 . 16 . 1 . 6	Gotri Jack Hammer	buah	49,000
5 . 9 . 5 . 16 . 1 . 7	Filter Oli	buah	293,000
5 . 9 . 5 . 16 . 1 . 8	Filter Solar	buah	293,000
5 . 9 . 5 . 16 . 1 . 9	Seal Hidrolik	buah	98,000
5 . 9 . 5 . 16 . 2	P.T.R		
5 . 9 . 5 . 16 . 2 . 1	Accu 12 V 120 AH	buah	2,438,000
5 . 9 . 5 . 17	BACK HOE NEW HOLLAND		
5 . 9 . 5 . 17 . 1	Rear Axle (Penggerak Roda Belakang)		
5 . 9 . 5 . 17 . 1 . 1	Shaft Klend Whell	buah	3,155,000
5 . 9 . 5 . 17 . 1 . 2	Bearing	buah	98,000
5 . 9 . 5 . 17 . 1 . 3	washer	buah	95,000
5 . 9 . 5 . 17 . 1 . 4	Spacer	buah	41,000
5 . 9 . 5 . 17 . 1 . 5	Driven Gear	buah	5,119,000
5 . 9 . 5 . 17 . 1 . 6	Shaft Whell	buah	7,322,000
5 . 9 . 5 . 17 . 2	Flexible Hose Excavator		
5 . 9 . 5 . 17 . 2 . 1	Flex. Hose Boom	buah	2,181,000
5 . 9 . 5 . 17 . 2 . 2	Flex. Hose Arm	buah	4,072,000
5 . 9 . 5 . 17 . 2 . 3	Flex. Hose Bucket	buah	2,430,000
5 . 9 . 5 . 17 . 2 . 4	Flex. Hose Swing	buah	3,738,000
5 . 9 . 5 . 17 . 2 . 5	Flex. Hose Stabiliser	buah	4,223,000
5 . 9 . 5 . 17 . 3	Flex. Hose Hydraulic System (Control Valve)		
5 . 9 . 5 . 17 . 3 . 1	Flex. Hose	buah	3,606,000
5 . 9 . 5 . 17 . 4	Seal Kit Cylinder Hydraulic		
5 . 9 . 5 . 17 . 4 . 1	Seal Kit Cylinder Stabiliser	set	1,355,000
5 . 9 . 5 . 17 . 4 . 2	Seal Kit Cylinder Swing	set	4,465,000
5 . 9 . 5 . 17 . 4 . 3	Seal Kit Cylinder Boom	set	5,345,000
5 . 9 . 5 . 17 . 4 . 4	Seal Kit Cylinder Arm	set	8,252,000
5 . 9 . 5 . 17 . 5	Control Valve Rear		
5 . 9 . 5 . 17 . 5 . 1	O-Ring	set	129,000
5 . 9 . 5 . 17 . 6	Filter Element		
5 . 9 . 5 . 17 . 6 . 1	Fuel Filter	buah	610,000
5 . 9 . 5 . 17 . 6 . 2	Oil Filter - Engine	buah	164,000
5 . 9 . 5 . 17 . 6 . 3	Oil Filter - Hydraulic	buah	1,313,000
5 . 9 . 5 . 17 . 6 . 4	Air Filter	buah	824,000
5 . 9 . 5 . 17 . 6 . 5	Air Filter	buah	1,472,000
5 . 9 . 5 . 18 .	BACK HOE JCB 4CX		
5 . 9 . 5 . 18 . 1	Flexible Hose Excavator		
5 . 9 . 5 . 18 . 1 . 1	Flex. Hose Boom	buah	3,094,000
5 . 9 . 5 . 18 . 1 . 2	Flex. Hose Arm	buah	2,722,000
5 . 9 . 5 . 18 . 1 . 3	Flex. Hose Bucket	buah	1,401,000
5 . 9 . 5 . 18 . 1 . 4	Flex. Hose Swing	buah	1,234,000
5 . 9 . 5 . 18 . 1 . 5	Flex. Hose Loader Arm	buah	940,000
5 . 9 . 5 . 18 . 2	Seal Kit Cylinder Hydraulic		
5 . 9 . 5 . 18 . 2 . 1	Seal Kit Cylinder Stabiliser	set	871,000
5 . 9 . 5 . 18 . 2 . 2	Seal Kit Cylinder Swing	set	1,130,000
5 . 9 . 5 . 18 . 2 . 3	Seal Kit Cylinder Boom	set	1,518,000
5 . 9 . 5 . 18 . 2 . 4	Seal Kit Cylinder Arm	set	1,386,000
5 . 9 . 5 . 18 . 2 . 5	Seal Kit Cylinder Bucket Mono	set	1,150,000
5 . 9 . 5 . 18 . 3	Control Valve		
5 . 9 . 5 . 18 . 3 . 1	Repair Kit, Valve Spool	set	9,061,000
5 . 9 . 5 . 18 . 3 . 2	Repair Kit, Dust Boot	set	4,195,000
5 . 9 . 5 . 18 . 4	Filter Element		
5 . 9 . 5 . 18 . 4 . 1	Fuel Filter	buah	264,000

NO. INDEKS	JENIS / NAMA BARANG	SATUAN	HARGA
5 . 9 . 5 . 18 . 4 . 2	Oil Filter - Engine	buah	191,000
5 . 9 . 5 . 18 . 4 . 3	Oil Filter - Hydraulic	buah	1,616,000
5 . 9 . 5 . 18 . 4 . 4	Air Filter	buah	1,066,000
5 . 9 . 5 . 18 . 5	Bucket		
5 . 9 . 5 . 18 . 5 . 1	Tooth Shank	buah	993,000
5 . 9 . 5 . 18 . 5 . 2	Tooth Tip	buah	452,000
5 . 9 . 5 . 18 . 5 . 3	Pin	buah	83,000
5 . 9 . 5 . 18 . 6	Loader		
5 . 9 . 5 . 18 . 6 . 1	Tooth Flex	buah	678,000
5 . 9 . 5 . 18 . 7	Dipper (Stick) Mono		
5 . 9 . 5 . 18 . 7 . 1	Link, Tipping	buah	8,811,000
5 . 9 . 5 . 19 .	SOVEL LOADER		
5 . 9 . 5 . 19 . 1	Handle And Shift Lever		
5 . 9 . 5 . 19 . 1 . 1	Orbit Roll	unit	57,935,000
5 . 9 . 5 . 19 . 2	Transmission Case		
5 . 9 . 5 . 19 . 2 . 1	Flex. Hose	buah	8,195,000
5 . 9 . 5 . 19 . 3	1 st, 2nd, 3rd and Reverse Clutch		
5 . 9 . 5 . 19 . 3 . 1	Plate Pressure	buah	4,902,000
5 . 9 . 5 . 19 . 3 . 2	Plate Clutch	buah	2,279,000
5 . 9 . 5 . 19 . 3 . 3	Ring Seal	set	4,557,000
5 . 9 . 5 . 19 . 4	Output Shaft		
5 . 9 . 5 . 19 . 4 . 1	Seal Oil	set	1,333,000
5 . 9 . 5 . 19 . 4 . 2	O-Ring	set	1,073,000
5 . 9 . 5 . 19 . 5	Hoist Cylinder		
5 . 9 . 5 . 19 . 5 . 1	Seal Kit	set	5,361,000
5 . 9 . 5 . 19 . 5 . 2	Holder	buah	3,404,000
5 . 9 . 5 . 19 . 5 . 3	Bushing	buah	2,286,000
5 . 9 . 5 . 19 . 5 . 4	Packing	buah	640,000
5 . 9 . 5 . 19 . 6	Bucket Cylinder		
5 . 9 . 5 . 19 . 6 . 1	Seal Kit	set	6,395,000
5 . 9 . 5 . 19 . 6 . 2	Holder	buah	3,404,000
5 . 9 . 5 . 19 . 6 . 3	Bushing	buah	2,286,000
5 . 9 . 5 . 19 . 6 . 4	Packing	buah	640,000
5 . 9 . 5 . 20 .	Truck Toyota Dyna-Rino		
5 . 9 . 5 . 20 . 1	Filter Udara	bh	114,000
5 . 9 . 5 . 20 . 2	Filter Solar Atas	bh	78,000
5 . 9 . 5 . 20 . 3	Filter Solar Bawah	bh	133,000
5 . 9 . 5 . 20 . 4	Filter Oil	bh	125,000
5 . 9 . 5 . 20 . 5	Seal Roda Depan Luar	bh	39,000
5 . 9 . 5 . 20 . 6	Seal Roda Depan Dalam	bh	102,000
5 . 9 . 5 . 20 . 7	Seal Roda Depan Dalam	bh	141,000
5 . 9 . 5 . 20 . 8	Seal Roda Depan Luar	bh	55,000
5 . 9 . 5 . 20 . 9	Bearing Roda Depan Luar	bh	203,000
5 . 9 . 5 . 20 . 10	Bearing Roda Depan Dalam	bh	188,000
5 . 9 . 5 . 20 . 11	Bearing Roda Belakang Luar	bh	411,000
5 . 9 . 5 . 20 . 12	Bearing Roda Belakang Dalam	bh	383,000
5 . 9 . 5 . 20 . 13	Plendes / MATAHARI "GEUNE"	bh	1,035,000
5 . 9 . 5 . 20 . 14	Plat Kopling "GEUNE"	bh	931,000
5 . 9 . 5 . 20 . 15	Drag Laker "NACHI"	bh	671,000
5 . 9 . 5 . 20 . 16	Dongkrak 20 Ton "APN"	bh	476,000
5 . 9 . 5 . 20 . 17	Van belt	bh	110,000
5 . 9 . 5 . 20 . 18	Engine Mounting	bh	182,000
5 . 9 . 5 . 20 . 19	Water Pump	bh	819,000
5 . 9 . 5 . 20 . 20	Kampas Rem Belakang	bh	323,000
5 . 9 . 5 . 20 . 21	Kampas Rem Depan	bh	297,000
5 . 9 . 5 . 20 . 22	Kabel PTO	bh	237,000
5 . 9 . 5 . 20 . 23	Accu 12 V.70 AH	bh	1,337,000
5 . 9 . 5 . 20 . 24	Master Kopling	bh	676,000
5 . 9 . 5 . 20 . 25	Per set	set	4,732,000
5 . 9 . 5 . 20 . 26	Mika Lampu Belakang	bh	71,000
5 . 9 . 5 . 20 . 27	Oil Seal Inner	bh	358,000
5 . 9 . 5 . 20 . 28	Bearing Outer Rear Axle	bh	693,000
5 . 9 . 5 . 20 . 29	Bearing Inner Rear Axle	bh	819,000
5 . 9 . 5 . 20 . 30	Front Hub and Drum		
5 . 9 . 5 . 20 . 30 . 1	Oil Seal Front Hub	bh	107,000
5 . 9 . 5 . 20 . 30 . 2	Bearing Outer Rear Axle	bh	400,000
5 . 9 . 5 . 20 . 30 . 3	Bearing Inner Rear Axle	bh	651,000
5 . 9 . 5 . 21 .	Truck Hino Dutro 130 HD		
5 . 9 . 5 . 21 . 1	Per		
5 . 9 . 5 . 21 . 1 . 1	Per depan no.1	buah	381,000
5 . 9 . 5 . 21 . 1 . 2	Per depan no.2	buah	488,000
5 . 9 . 5 . 21 . 1 . 3	Per depan no.3	buah	289,000
5 . 9 . 5 . 21 . 1 . 4	Per depan no.4	buah	158,000
5 . 9 . 5 . 21 . 1 . 5	Per depan no.5	buah	128,000
5 . 9 . 5 . 21 . 1 . 6	Per depan no.6	buah	83,000
5 . 9 . 5 . 21 . 1 . 7	Per help belakang no.1	buah	270,000
5 . 9 . 5 . 21 . 1 . 8	Per help belakang no.2	buah	498,000
5 . 9 . 5 . 21 . 1 . 9	Per help belakang no.3	buah	158,000
5 . 9 . 5 . 21 . 1 . 10	Per help belakang no.4	buah	148,000
5 . 9 . 5 . 21 . 1 . 11	Per help belakang no.5	buah	122,000

NO. INDEKS	JENIS / NAMA BARANG	SATUAN	HARGA
5 . 9 . 5 . 21 . 1 . 12	Per help belakang no.6	buah	101,000
5 . 9 . 5 . 21 . 1 . 13	Per babon belakang no. 1	buah	1,090,000
5 . 9 . 5 . 21 . 1 . 14	Per babon belakang no. 2	buah	315,000
5 . 9 . 5 . 21 . 1 . 15	Per babon belakang no. 3	buah	290,000
5 . 9 . 5 . 21 . 1 . 16	Per babon belakang no. 4	buah	249,000
5 . 9 . 5 . 21 . 1 . 17	Per babon belakang no. 5	buah	219,000
5 . 9 . 5 . 21 . 1 . 18	Per babon belakang no. 6	buah	209,000
5 . 9 . 5 . 21 . 1 . 19	Baud torn	buah	72,000
5 . 9 . 5 . 21 . 1 . 20	Begel	buah	265,000
5 . 9 . 5 . 21 . 1 . 21	Anting per	buah	366,000
5 . 9 . 5 . 21 . 1 . 22	Stoper / karet susu	buah	1,887,000
5 . 9 . 5 . 21 . 1 . 23	Bosh anting per (1 anting)	buah	325,000
5 . 9 . 5 . 21 . 1 . 24	Pen per (1 anting)	buah	257,000
5 . 9 . 5 . 21 . 1 . 25	Karet Anting Per (1 Per)	buah	226,000
5 . 9 . 5 . 21 . 1 . 26	Shock breaker depan	buah	218,000
5 . 9 . 5 . 21 . 1 . 27	Shock breaker belakang	buah	260,000
5 . 9 . 5 . 21 . 2	Rem		
5 . 9 . 5 . 21 . 2 . 1	Kampas rem depan (1 roda)	2 pcs	169,000
5 . 9 . 5 . 21 . 2 . 2	Whell cylinder depan (1 roda)	1 pcs	854,000
5 . 9 . 5 . 21 . 2 . 3	Keep rem depan (1 roda)	2 pcs	45,000
5 . 9 . 5 . 21 . 2 . 4	Kampas rem belakang (1 roda)	2 pcs	58,000
5 . 9 . 5 . 21 . 2 . 5	Whellcylinder belakang (1 roda)	1 pcs	1,209,000
5 . 9 . 5 . 21 . 2 . 6	Keep rem belakang (1 roda)	1 pcs	51,000
5 . 9 . 5 . 21 . 2 . 7	Kabel hand rem	buah	315,000
5 . 9 . 5 . 21 . 2 . 8	Tromol hand rem	buah	752,000
5 . 9 . 5 . 21 . 2 . 9	Braket hand rem	buah	1,880,000
5 . 9 . 5 . 21 . 2 . 10	Kampas hand rem (2 pcs)	2 pcs	1,067,000
5 . 9 . 5 . 21 . 2 . 11	Reparkit master rem atas	buah	488,000
5 . 9 . 5 . 21 . 2 . 12	Reparkit master rem bawah	buah	488,000
5 . 9 . 5 . 21 . 2 . 13	Pipe rem depan	buah	630,000
5 . 9 . 5 . 21 . 2 . 14	Pipe rem belakang	buah	356,000
5 . 9 . 5 . 21 . 2 . 15	Central rem	buah	2,388,000
5 . 9 . 5 . 21 . 2 . 16	Laker roda belakang luar (1 roda)	buah	441,000
5 . 9 . 5 . 21 . 2 . 17	Laker roda belakang dalam (1 roda)	buah	417,000
5 . 9 . 5 . 21 . 2 . 18	Seal roda belakang luar (1 roda)	buah	46,000
5 . 9 . 5 . 21 . 2 . 19	Seal roda belakang dalam (1 roda)	buah	356,000
5 . 9 . 5 . 21 . 2 . 20	Tromol roda belakang (1 roda)	buah	1,067,000
5 . 9 . 5 . 21 . 2 . 21	Nap roda belakang (1 roda)	buah	1,220,000
5 . 9 . 5 . 21 . 2 . 22	Well boot belakang (1 roda)	4 pcs	51,000
5 . 9 . 5 . 21 . 2 . 23	Per kampas roda belakang	1 pcs	72,000
5 . 9 . 5 . 21 . 2 . 24	Laker roda depan luar (1 roda)	buah	160,000
5 . 9 . 5 . 21 . 2 . 25	Laker roda depan dalam (1 roda)	buah	407,000
5 . 9 . 5 . 21 . 2 . 26	Seal roda depan luar (1 roda)	buah	100,000
5 . 9 . 5 . 21 . 2 . 27	Seal roda depan dalam (1 roda)	buah	92,000
5 . 9 . 5 . 21 . 2 . 28	Tromol roda depan (1 roda)	buah	894,000
5 . 9 . 5 . 21 . 2 . 29	Well boot depan (1 roda)	2 pcs	45,000
5 . 9 . 5 . 21 . 2 . 30	Per kampas roda depan	1 pcs	79,000
5 . 9 . 5 . 21 . 2 . 31	Mur baut roda (1 roda)	1 pcs	72,000
5 . 9 . 5 . 21 . 2 . 32	As roda belakang (1 roda)	buah	1,225,000
5 . 9 . 5 . 21 . 2 . 33	Blower rem	buah	10,972,000
5 . 9 . 5 . 21 . 2 . 34	King pen	1 pcs	661,000
5 . 9 . 5 . 21 . 2 . 35	Tie rod	1 pcs	134,000
5 . 9 . 5 . 21 . 2 . 36	Long Tie rod	buah	280,000
5 . 9 . 5 . 21 . 2 . 37	Servo rem	buah	10,972,000
5 . 9 . 5 . 21 . 2 . 38	Join yoke	1 pcs	600,000
5 . 9 . 5 . 21 . 2 . 39	Pelg (1 roda)	buah	1,626,000
5 . 9 . 5 . 21 . 2 . 40	Switch break rem / solenoid exhst. Brake	buah	549,000
5 . 9 . 5 . 21 . 2 . 41	Break rem / exhaust brake	buah	1,829,000
5 . 9 . 5 . 21 . 2 . 42	Adjuster Hand Rem	buah	629,000
5 . 9 . 5 . 21 . 3	Kopling & Perseneling		
5 . 9 . 5 . 21 . 3 . 1	Kampas kopling	buah	872,000
5 . 9 . 5 . 21 . 3 . 2	Drug laker	buah	1,067,000
5 . 9 . 5 . 21 . 3 . 3	Plendes	buah	850,000
5 . 9 . 5 . 21 . 3 . 4	Master kopling atas (assy)	buah	1,372,000
5 . 9 . 5 . 21 . 3 . 5	Master kopling bawah (assy)	buah	651,000
5 . 9 . 5 . 21 . 3 . 6	Joint Flange Perseneling	buah	832,000
5 . 9 . 5 . 21 . 3 . 7	Teirod Perseneling	buah	553,000
5 . 9 . 5 . 21 . 3 . 8	Bearing perseneling	buah	148,000
5 . 9 . 5 . 21 . 3 . 9	Cyncromes renteng	buah	1,328,000
5 . 9 . 5 . 21 . 3 . 10	Gigi sincromes no.1	buah	1,220,000
5 . 9 . 5 . 21 . 3 . 11	Gigi sincromes no.2	buah	1,220,000
5 . 9 . 5 . 21 . 3 . 12	Gigi sincromes no.3	buah	346,000
5 . 9 . 5 . 21 . 3 . 13	Gigi sincromes no.4	buah	295,000
5 . 9 . 5 . 21 . 3 . 14	Gigi sincromes no.5	buah	244,000
5 . 9 . 5 . 21 . 3 . 15	Cyncromes ring	buah	1,220,000
5 . 9 . 5 . 21 . 3 . 16	Gigi perseneling no.1	buah	1,677,000
5 . 9 . 5 . 21 . 3 . 17	Gigi perseneling no.2	buah	1,727,000
5 . 9 . 5 . 21 . 3 . 18	Gigi perseneling no.3	buah	966,000
5 . 9 . 5 . 21 . 3 . 19	Gigi perseneling no.4	buah	7,518,000
5 . 9 . 5 . 21 . 3 . 20	Gigi lima	buah	1,077,000

NO. INDEKS	JENIS / NAMA BARANG	SATUAN	HARGA
5 . 9 . 5 . 21 . 3 . 21	Shaft output (Asprice)	buah	2,896,000
5 . 9 . 5 . 21 . 3 . 22	Shaft input (As direct)	buah	4,318,000
5 . 9 . 5 . 21 . 3 . 23	Gigi renteng	buah	3,038,000
5 . 9 . 5 . 21 . 3 . 24	Gigi Reverse	buah	1,626,000
5 . 9 . 5 . 21 . 3 . 25	Transmisi Mounting	buah	399,000
5 . 9 . 5 . 21 . 3 . 26	Packing Perseneling	buah	105,000
5 . 9 . 5 . 21 . 3 . 27	Seal perseneling	buah	112,000
5 . 9 . 5 . 21 . 3 . 28	Kres copel gardan	buah	966,000
5 . 9 . 5 . 21 . 3 . 29	Selang Flexibel Kopling	buah	435,000
5 . 9 . 5 . 21 . 3 . 30	Laker gandul	buah	549,000
5 . 9 . 5 . 21 . 3 . 31	Drug Laker Gandul	buah	377,000
5 . 9 . 5 . 21 . 3 . 32	Spie Praon	buah	29,000
5 . 9 . 5 . 21 . 3 . 33	Seal As price	buah	79,000
5 . 9 . 5 . 21 . 3 . 34	Seal direct	buah	26,000
5 . 9 . 5 . 21 . 3 . 35	Kancingan Drug Laker	buah	88,000
5 . 9 . 5 . 21 . 3 . 36	Laker laces perseneling	buah	569,000
5 . 9 . 5 . 21 . 3 . 37	Seal PTO Perseneling	buah	111,000
5 . 9 . 5 . 21 . 3 . 38	Unit Perseneling	set	12,578,000
5 . 9 . 5 . 21 . 3 . 39	Cover Transmisi	buah	1,503,000
5 . 9 . 5 . 21 . 3 . 40	PTO	buah	6,289,000
5 . 9 . 5 . 21 . 3 . 41	Kabel PTO	buah	810,000
5 . 9 . 5 . 21 . 3 . 42	Laker kroncong	buah	569,000
5 . 9 . 5 . 21 . 3 . 43	Pangkon Perseneling	buah	677,000
5 . 9 . 5 . 21 . 3 . 44	Tierod Perseneling	buah	350,000
5 . 9 . 5 . 21 . 3 . 45	Baud drug group	buah	10,000
5 . 9 . 5 . 21 . 3 . 46	Crescopel Gardan	buah	490,000
5 . 9 . 5 . 21 . 3 . 47	Kancingan Drug Laker	buah	88,000
5 . 9 . 5 . 21 . 3 . 48	Laker Sasis Perseneling	buah	420,000
5 . 9 . 5 . 21 . 3 . 49	Tongkat perseneling	buah	569,000
5 . 9 . 5 . 21 . 3 . 50	Repairkit master kopling atas	buah	117,000
5 . 9 . 5 . 21 . 3 . 51	Repairkit master kopling bawah	buah	163,000
5 . 9 . 5 . 21 . 3 . 52	Ganti oli transmisi	liter	100,000
5 . 9 . 5 . 21 . 3 . 53	Karter	buah	569,000
5 . 9 . 5 . 21 . 3 . 54	Packing Kalter	buah	175,000
5 . 9 . 5 . 21 . 3 . 55	Kabel transmisi pemindah	buah	691,000
5 . 9 . 5 . 21 . 3 . 56	Kabel transmisi pemilih	buah	549,000
5 . 9 . 5 . 21 . 4	Gardan		
5 . 9 . 5 . 21 . 4 . 1	Unit gardan (assy)	buah	42,251,000
5 . 9 . 5 . 21 . 4 . 2	Satelit gardan besar	buah	854,000
5 . 9 . 5 . 21 . 4 . 3	Satelit gardan kecil	buah	600,000
5 . 9 . 5 . 21 . 4 . 4	Spider	buah	966,000
5 . 9 . 5 . 21 . 4 . 5	Brearing deferensial	buah	823,000
5 . 9 . 5 . 21 . 4 . 6	Brearing gardan	buah	823,000
5 . 9 . 5 . 21 . 4 . 7	Seal gardan	buah	280,000
5 . 9 . 5 . 21 . 4 . 8	Flange drive pinion	buah	1,067,000
5 . 9 . 5 . 21 . 4 . 9	Washer deferansial	buah	57,000
5 . 9 . 5 . 21 . 4 . 10	Gear kit gardan	buah	15,543,000
5 . 9 . 5 . 21 . 4 . 11	Crown whell pinion	buah	5,669,000
5 . 9 . 5 . 21 . 4 . 12	Plat laker pinion	buah	12,000
5 . 9 . 5 . 21 . 4 . 13	Ring pinion besar	buah	72,000
5 . 9 . 5 . 21 . 4 . 14	Ring pinion kecil	buah	61,000
5 . 9 . 5 . 21 . 4 . 15	York sleve	buah	712,000
5 . 9 . 5 . 21 . 4 . 16	Pinion	buah	478,000
5 . 9 . 5 . 21 . 4 . 17	Gear pinion	buah	854,000
5 . 9 . 5 . 21 . 4 . 18	Gear	buah	854,000
5 . 9 . 5 . 21 . 4 . 19	Nap roda belakang	buah	18,000
5 . 9 . 5 . 21 . 4 . 20	Packing nap roda	buah	18,000
5 . 9 . 5 . 21 . 4 . 21	Seal nap roda (luar)	buah	366,000
5 . 9 . 5 . 21 . 4 . 22	Seal nap roda (dalam)	buah	46,000
5 . 9 . 5 . 21 . 4 . 23	Ganti oli gardan	liter	196,000
5 . 9 . 5 . 21 . 5	Kabin		
5 . 9 . 5 . 21 . 5 . 1	Kaca depan	buah	935,000
5 . 9 . 5 . 21 . 5 . 2	Sikat kaca	buah	92,000
5 . 9 . 5 . 21 . 5 . 3	Reting depan (1 lampu)	buah	244,000
5 . 9 . 5 . 21 . 5 . 4	Reting belakang (1 lampu)	buah	244,000
5 . 9 . 5 . 21 . 5 . 5	Lampu depan (1 lampu)	buah	834,000
5 . 9 . 5 . 21 . 5 . 6	Pelg	buah	1,626,000
5 . 9 . 5 . 21 . 5 . 7	Ring pelg	buah	224,000
5 . 9 . 5 . 21 . 5 . 8	Sock breaker belakang	buah	199,000
5 . 9 . 5 . 21 . 5 . 9	Baud sockbreaker	buah	16,000
5 . 9 . 5 . 21 . 5 . 10	Baud kopel	buah	20,000
5 . 9 . 5 . 21 . 5 . 11	Joint kopel	buah	1,321,000
5 . 9 . 5 . 21 . 5 . 12	Pengaman Roda Samping	buah	2,705,000
5 . 9 . 5 . 21 . 5 . 13	Slebor Belakang	set	2,516,000
5 . 9 . 5 . 21 . 5 . 14	Dinamo wiper	buah	641,000
5 . 9 . 5 . 21 . 5 . 15	Kendangan knalpot	buah	1,524,000
5 . 9 . 5 . 21 . 5 . 16	Gulu banyak knalpot	buah	437,000
5 . 9 . 5 . 21 . 5 . 17	Pipa knalpot	buah	2,083,000
5 . 9 . 5 . 21 . 5 . 18	Packing knalpot	buah	178,000
5 . 9 . 5 . 21 . 5 . 19	Packing manipol	buah	101,000

NO. INDEKS	JENIS / NAMA BARANG	SATUAN	HARGA
5 . 9 . 5 . 21 . 5 . 20	Spion	buah	100,000
5 . 9 . 5 . 21 . 5 . 21	Klakson	buah	148,000
5 . 9 . 5 . 21 . 5 . 22	Kabel body	buah	1,220,000
5 . 9 . 5 . 21 . 5 . 23	Kabel speedometer	buah	244,000
5 . 9 . 5 . 21 . 5 . 24	Tutup tangki	buah	300,000
5 . 9 . 5 . 21 . 5 . 25	Baut knalpot	buah	16,000
5 . 9 . 5 . 21 . 5 . 26	Dongkrak	buah	844,000
5 . 9 . 5 . 21 . 5 . 27	Kunci roda	buah	366,000
5 . 9 . 5 . 21 . 5 . 28	Relay lampu belakang	buah	300,000
5 . 9 . 5 . 21 . 5 . 29	Relay starter	buah	440,000
5 . 9 . 5 . 21 . 5 . 30	Relay lampu kepala	buah	356,000
5 . 9 . 5 . 21 . 5 . 31	Handle pintu	buah	168,000
5 . 9 . 5 . 21 . 5 . 32	Regulator pintu	buah	1,067,000
5 . 9 . 5 . 21 . 5 . 33	Accu 60 A	buah	1,188,000
5 . 9 . 5 . 21 . 5 . 34	Accu 100 A	buah	1,677,000
5 . 9 . 5 . 21 . 5 . 35	Kabel Accu pendek (kabel mesin no. 3)	buah	214,000
5 . 9 . 5 . 21 . 5 . 36	Kabel starter (kabel mesin no. 2)	buah	702,000
5 . 9 . 5 . 21 . 5 . 37	Kabel mesin utama	buah	2,083,000
5 . 9 . 5 . 21 . 5 . 38	Kabel kabin (kabel atas boks sekering)	buah	1,118,000
5 . 9 . 5 . 21 . 5 . 39	Klem Accu	buah	70,000
5 . 9 . 5 . 21 . 6	Mesin		
5 . 9 . 5 . 21 . 6 . 1	Water pump	buah	783,000
5 . 9 . 5 . 21 . 6 . 2	Ganti oli mesin	buah	458,000
5 . 9 . 5 . 21 . 6 . 3	Fuel pump (feed pump)	buah	36,000
5 . 9 . 5 . 21 . 6 . 4	Seal kruk as	buah	133,000
5 . 9 . 5 . 21 . 6 . 5	Selang Water Pump	buah	112,000
5 . 9 . 5 . 21 . 6 . 6	Selang Blower	buah	371,000
5 . 9 . 5 . 21 . 6 . 7	Ribil Dynamo Stater	buah	1,328,000
5 . 9 . 5 . 21 . 6 . 8	Fanbelt	buah	72,000
5 . 9 . 5 . 21 . 6 . 9	Oli pump	buah	1,270,000
5 . 9 . 5 . 21 . 6 . 10	Buring	buah	1,778,000
5 . 9 . 5 . 21 . 6 . 11	Seker	buah	457,000
5 . 9 . 5 . 21 . 6 . 12	Ring seker	buah	387,000
5 . 9 . 5 . 21 . 6 . 13	Packing silinder cop	buah	671,000
5 . 9 . 5 . 21 . 6 . 14	Metal jalan	buah	641,000
5 . 9 . 5 . 21 . 6 . 15	Metal duduk	buah	384,000
5 . 9 . 5 . 21 . 6 . 16	Metal bulan	buah	468,000
5 . 9 . 5 . 21 . 6 . 17	Packing full set	buah	2,195,000
5 . 9 . 5 . 21 . 6 . 18	Bushing stang seker	buah	70,000
5 . 9 . 5 . 21 . 6 . 19	Stang seker	buah	2,235,000
5 . 9 . 5 . 21 . 6 . 20	Busi pemanas	buah	140,000
5 . 9 . 5 . 21 . 6 . 21	Klep in	buah	194,000
5 . 9 . 5 . 21 . 6 . 22	Klep ex	buah	315,000
5 . 9 . 5 . 21 . 6 . 23	Pen piston	buah	126,000
5 . 9 . 5 . 21 . 6 . 24	Metal noken as	buah	378,000
5 . 9 . 5 . 21 . 6 . 25	Pen seker	buah	126,000
5 . 9 . 5 . 21 . 6 . 26	Bosh Pen Seker	buah	70,000
5 . 9 . 5 . 21 . 6 . 27	Noken As	buah	1,595,000
5 . 9 . 5 . 21 . 6 . 28	Kruk AS	buah	11,429,000
5 . 9 . 5 . 21 . 6 . 29	Swict oli	buah	300,000
5 . 9 . 5 . 21 . 6 . 30	Pleeg glow	buah	51,000
5 . 9 . 5 . 21 . 6 . 31	Crank shaft	buah	11,429,000
5 . 9 . 5 . 21 . 6 . 32	Liner	buah	1,778,000
5 . 9 . 5 . 21 . 6 . 33	Valve Exhaust	buah	315,000
5 . 9 . 5 . 21 . 6 . 34	Seal kruk as	buah	133,000
5 . 9 . 5 . 21 . 6 . 35	Valve intake	buah	194,000
5 . 9 . 5 . 21 . 6 . 36	Cylinder blok	buah	36,064,000
5 . 9 . 5 . 21 . 6 . 37	Templar	buah	234,000
5 . 9 . 5 . 21 . 6 . 38	Pipe injektion	buah	712,000
5 . 9 . 5 . 21 . 6 . 39	Engine mounting	buah	101,000
5 . 9 . 5 . 21 . 6 . 40	Transmisi Mounting	buah	420,000
5 . 9 . 5 . 21 . 6 . 41	Radiator	buah	2,185,000
5 . 9 . 5 . 21 . 6 . 42	Selang termostart	buah	46,000
5 . 9 . 5 . 21 . 6 . 43	Klem selang radiator	buah	31,000
5 . 9 . 5 . 21 . 6 . 44	Gasket Oil Pump	buah	17,000
5 . 9 . 5 . 21 . 6 . 45	Kabel gas	buah	168,000
5 . 9 . 5 . 21 . 6 . 46	Selang solar	buah	90,000
5 . 9 . 5 . 21 . 6 . 47	Tangki solar	buah	1,067,000
5 . 9 . 5 . 21 . 6 . 48	Filter oli	buah	71,000
5 . 9 . 5 . 21 . 6 . 49	Filter solar	buah	39,000
5 . 9 . 5 . 21 . 6 . 50	PTO	buah	6,289,000
5 . 9 . 5 . 21 . 6 . 51	Hose valve / Cover klep	buah	437,000
5 . 9 . 5 . 21 . 7	Hydrolic		
5 . 9 . 5 . 21 . 7 . 1	Seal boom hidrolis	buah	143,000
5 . 9 . 5 . 21 . 7 . 2	Krescopel hidrolis	buah	305,000
5 . 9 . 5 . 21 . 7 . 3	Seal tutup boom	buah	77,000
5 . 9 . 5 . 21 . 7 . 4	Selang hidrolis panjang	buah	432,000
5 . 9 . 5 . 21 . 7 . 5	Selang hidrolis pendek	buah	381,000
5 . 9 . 5 . 21 . 7 . 6	Sambungan pompa	buah	305,000
5 . 9 . 5 . 21 . 7 . 7	Cek valve	buah	1,372,000

NO. INDEKS	JENIS / NAMA BARANG	SATUAN	HARGA
5 . 9 . 5 . 21 . 7 . 8	Center balance	buah	762,000
5 . 9 . 5 . 21 . 7 . 9	As pompa hidrolis	buah	255,000
5 . 9 . 5 . 21 . 7 . 10	Piston boom hidrolis	buah	61,000
5 . 9 . 5 . 21 . 7 . 11	Seal pompa hidrolis	buah	153,000
5 . 9 . 5 . 21 . 7 . 12	Oring atas / Bawah	buah	318,000
5 . 9 . 5 . 21 . 7 . 13	Tutup boom hidrolis	buah	77,000
5 . 9 . 5 . 21 . 7 . 14	Nepel el bon	buah	191,000
5 . 9 . 5 . 21 . 7 . 15	Nepel pompa	buah	77,000
5 . 9 . 5 . 21 . 7 . 16	Nepel hidrolic	buah	51,000
5 . 9 . 5 . 21 . 7 . 17	Overhoul hydrolic	buah	868,000
5 . 9 . 5 . 21 . 8	Dinamo Amper & Starter		
5 . 9 . 5 . 21 . 8 . 1	Laker dynamo stater		140,000
5 . 9 . 5 . 21 . 8 . 2	Otomatis dynamo stater		1,654,000
5 . 9 . 5 . 21 . 8 . 3	Regulator dynamo stater		909,000
5 . 9 . 5 . 21 . 8 . 4	Bendix stater		1,363,000
5 . 9 . 5 . 21 . 8 . 5	Unit dynamo Amper		3,891,000
5 . 9 . 5 . 21 . 8 . 6	Unit dynamo Stater		3,891,000
5 . 9 . 5 . 21 . 8 . 7	Angker dynamo stater		1,609,000
5 . 9 . 5 . 21 . 8 . 8	Ketot dynamo amper		5,710,000
5 . 9 . 5 . 21 . 8 . 9	Colboster		397,000
5 . 9 . 5 . 21 . 8 . 10	IC dynamo amper		5,710,000
5 . 9 . 5 . 21 . 8 . 11	Magnetic swict dynamo stater		1,697,000
5 . 9 . 5 . 21 . 9	Boshpomp		
5 . 9 . 5 . 21 . 9 . 1	Unit injection pump (assy)	buah	5,232,000
5 . 9 . 5 . 21 . 9 . 2	Test injection pump	buah	407,000
5 . 9 . 5 . 21 . 9 . 3	Ring washer injection pump	buah	31,000
5 . 9 . 5 . 21 . 9 . 4	Plunyer	buah	346,000
5 . 9 . 5 . 21 . 9 . 5	Valve	buah	194,000
5 . 9 . 5 . 21 . 9 . 6	Nozel	buah	864,000
5 . 9 . 5 . 21 . 9 . 7	Packing injection pump	buah	5,000
5 . 9 . 5 . 21 . 9 . 8	Solenoid	buah	521,000
5 . 9 . 5 . 21 . 9 . 9	Seal injection pump	buah	49,000
5 . 9 . 5 . 21 . 9 . 10	Selang injection pump	buah	138,000
5 . 9 . 5 . 21 . 9 . 11	Hose full injection	buah	102,000
5 . 9 . 5 . 21 . 9 . 12	Pipe injection pump	buah	458,000
5 . 9 . 5 . 21 . 9 . 13	Roller	buah	175,000
5 . 9 . 5 . 21 . 10	Radiator		
5 . 9 . 5 . 21 . 10 . 1	Unit radiator	buah	2,185,000
5 . 9 . 5 . 21 . 10 . 2	Klem selang radiator	buah	31,000
5 . 9 . 5 . 21 . 10 . 3	Selang radiator atas	buah	46,000
5 . 9 . 5 . 21 . 10 . 4	Selang radiator bawah	buah	112,000
5 . 9 . 5 . 21 . 10 . 5	Tutup radiator	buah	58,000
5 . 9 . 5 . 21 . 10 . 6	Seal klep	buah	2,235,000
5 . 9 . 5 . 21 . 10 . 7	Packing kalter	buah	874,000
5 . 9 . 5 . 21 . 10 . 8	Sulingan templar	buah	580,000
5 . 9 . 5 . 21 . 10 . 9	Packing cylindercop	buah	671,000
5 . 9 . 5 . 21 . 10 . 10	Packing deksel	buah	111,000
5 . 9 . 5 . 21 . 10 . 11	Selang termostart	buah	46,000
5 . 9 . 5 . 21 . 10 . 12	Ribil Cylindercop	buah	3,156,000
5 . 9 . 5 . 21 . 10 . 13	Slep Kruk As	buah	1,654,000
5 . 9 . 5 . 21 . 11	Understel		
5 . 9 . 5 . 21 . 11 . 1	Worm steer		4,420,000
5 . 9 . 5 . 21 . 11 . 2	Knucle steer		1,281,000
5 . 9 . 5 . 21 . 11 . 3	Hanger Steer		1,202,000
5 . 9 . 5 . 21 . 11 . 4	Drug link		678,000
5 . 9 . 5 . 21 . 12	Filter		
5 . 9 . 5 . 21 . 12 . 1	Filter Oli	buah	112,000
5 . 9 . 5 . 21 . 12 . 2	Filter Udara	buah	90,000
5 . 9 . 5 . 21 . 12 . 3	Filter Solar Atas	buah	51,000
5 . 9 . 5 . 21 . 12 . 4	Filter Solar Bawah	buah	94,000
5 . 9 . 5 . 21 . 12 . 5	Ban Luar - GT (750/16/14)	buah	1,976,000
5 . 9 . 5 . 21 . 12 . 6	Ban Dalam	buah	214,000
5 . 9 . 5 . 21 . 12 . 7	Selendang	buah	85,000
5 . 9 . 5 . 22	CATERPILLAR M 313 D		
5 . 9 . 5 . 22 . 1	Filter Oli Primer	buah	350,700
5 . 9 . 5 . 22 . 2	Filter Oli Sekunder	buah	218,400
5 . 9 . 5 . 22 . 3	Filter Solar Primer	buah	624,800
5 . 9 . 5 . 22 . 4	Filter Solar Sekunder	buah	458,900
5 . 9 . 5 . 22 . 5	Filter Udara	buah	1,848,000
5 . 9 . 5 . 23	HYUNDAI ROBEX 140W-9S		
5 . 9 . 5 . 23 . 1	Filter Oli Primer	buah	175,400
5 . 9 . 5 . 23 . 2	Filter Oli Sekunder	buah	230,000
5 . 9 . 5 . 23 . 3	Filter Solar Primer	buah	535,500
5 . 9 . 5 . 23 . 4	Filter Solar Sekunder	buah	392,700
5 . 9 . 5 . 23 . 5	Filter Udara	buah	1,732,500
5 . 9 . 5 . 23 . 6	Element Assy-F/Filter	buah	526,100
5 . 9 . 5 . 23 . 7	Filter - Fuel	buah	286,700
5 . 9 . 5 . 23 . 8	Filter-Fuel W/Separator	buah	286,700
5 . 9 . 5 . 23 . 9	Filter-Lub Oli	buah	423,200
5 . 9 . 5 . 23 . 10	Element-A/Cleaner In	buah	770,700

NO. INDEKS	JENIS / NAMA BARANG	SATUAN	HARGA
5 . 9 . 5 . 23 . 11	Element-A/Cleaner Out	buah	1,427,000
5 . 9 . 5 . 23 . 12	Element-Return Filter	buah	1,727,300
5 . 9 . 5 . 23 . 13	Filter Hydraulix	buah	1,727,300
5 . 9 . 5 . 23 . 14	Boom Cylinder Seal Kit	buah	1,277,900
5 . 9 . 5 . 23 . 15	Arm Cylinder Sela Kit	buah	1,661,100
5 . 9 . 5 . 23 . 16	Bucket Cylinder Seal Kit	buah	1,277,900
5 . 9 . 5 . 23 . 17	Poin Tooth	buah	458,900
5 . 9 . 5 . 23 . 18	Pin Tooth	buah	91,400
5 . 9 . 5 . 23 . 19	Side Cutter R	buah	972,300
5 . 9 . 5 . 23 . 20	Side Cutter L	buah	972,300
5 . 9 . 5 . 23 . 21	V Belt Engine	buah	533,400
5 . 9 . 5 . 23 . 22	V Belt Ac	buah	96,600
5 . 9 . 5 . 23 . 23	Ring Stone-Pesister	buah	3,916,500
5 . 9 . 5 . 23 . 24	Bearing Assy/Journal	buah	2,611,400
5 . 9 . 5 . 23 . 25	Cylinder Seal Kit	buah	1,393,400
5 . 9 . 5 . 24 .	WHEEL EXCAVATOR DX 140W DOOSAN		
5 . 9 . 5 . 24 . 1	Filter Oli	buah	131,300
5 . 9 . 5 . 24 . 2	Fuel Filter	buah	175,000
5 . 9 . 5 . 24 . 3	Pre Cleaner	buah	1,819,000
5 . 9 . 5 . 24 . 4	Air Cleaner	buah	2,028,000
5 . 9 . 5 . 24 . 5	Air Breather	buah	1,236,100
5 . 9 . 5 . 24 . 6	Point Tooth	buah	255,900
5 . 9 . 5 . 24 . 7	Water Separator	buah	299,100
5 . 9 . 5 . 24 . 8	Fuel Strainer	buah	294,000
5 . 9 . 5 . 24 . 9	Element Return Filter	buah	237,900
5 . 9 . 5 . 25 .	YANMAR EXCAVAROR		
5 . 9 . 5 . 25 . 1	Filter Oli	buah	361,700
5 . 9 . 5 . 25 . 2	Fuel Filter	buah	570,800
5 . 9 . 5 . 25 . 3	Hyd.Return Filter	buah	887,100
5 . 9 . 5 . 25 . 4	Hyd.Brether Filter	buah	447,300
5 . 9 . 5 . 25 . 5	Air Cleaner Outer	buah	496,500
5 . 9 . 5 . 25 . 6	Air Cleaner Inner	buah	436,000
5 . 9 . 5 . 25 . 7	Fuel Thank Filter	buah	583,400